

HIGHLAND CARE CENTER
4285 SOUTH HIGHLAND DRIVE
SALT LAKE CITY UT 84124
STATE'S REGION CODE: 001

PROVIDER #: 465078 FACILITY BEDS
PHONE NUMBER: (801) 278-2839
PARTICIPATION DATE: 09/01/1981 CERTIFIED: 73

TYPE ACTION: RECERTIFICATION
TOTAL: 108
TYPE OWNERSHIP: FOR PROFIT - CORPORATION

COMPLIANCE STATUS: FACILITY MEETS REQUIREMENTS BASED ON AN ACCEPTABLE PLAN OF CORRECTION

RESIDENT CENSUS ON 10/21/2004		LTC ADMISSION/SUSPENSION DATES		TOTAL CERTIFIED BEDS: 73			
TOTAL:	60	ADMISSION SUSPENDED:	18	18/19	19	ICF/MR	
MEDICARE:	55	SUSPENSION RESCINDED:	--	---	--	---	
MEDICAID:	0				73		
OTHER:	5						

CURRENT SURVEY REVISIT DATES - NONE

PRIOR 3 SURVEY	S/S CODE	PRIOR 2 SURVEY	S/S CODE	PRIOR 1 SURVEY	S/S CODE	CURRENT SURVEY	S/S CODE	PLAN/DATE OF CORRECT	PROGRAM REQUIREMENTS
12/2001		11/2002		12/2003		10/21/2004			
X	D			X	B	X P	B	12/15/2004	REQ F0281-SERVICES PROVIDED MEET PROFESSIONAL STANDARDS
						X P	B	12/15/2004	REQ F0309-PROVIDE NECESS CARE FOR HIGHEST PRAC WELL BEING
X	E			X	D				REQ F0326-RESIDENT RECEIVES THERAPEUTIC DIET WHEN REQUIRED
				X	E				REQ F0332-MEDICATION ERROR RATES OF 5% OR MORE
				X	E				REQ F0333-RESIDENTS FREE FROM SIGNIFICANT MED ERRORS
X	E			X	B				REQ F0371-STORE/PREPARE/DISTRIB FOOD UNDER SANITARY CONDS
									REQ F0426-FACILITY PROVIDES PHARMACEUTICAL SERVICES
									REQ F0460-ROOMS DESIGNED TO ASSURE FULL VISUAL PRIVACY

EDITION OF LSC APPLIED

85 EXIST	85 EXIST	2000 EXIS	2000 EXIS	CURRENT SURVEY	PLAN/DATE OF CORRECTION	LSC DEFICIENCIES - BLDG NO. 01
PRIOR 3 SURVEY	PRIOR 2 SURVEY	PRIOR 1 SURVEY	CURRENT SURVEY	PLAN/DATE OF CORRECTION		
12/2001	11/2002	12/2003	10/21/2004			
	X		X C	10/30/2004		K0025-SMOKE PARTITION CONSTRUCTION
	X		X C	10/30/2004		K0029-HAZARDOUS AREAS - SEPARATION
	X		X N	11/05/2004		K0046-EMERGENCY LIGHTING
X	X		X C			K0050-FIRE DRILLS
	X		X N			K0052-TESTING OF FIRE ALARM
	X		X N			K0056-AUTOMATIC SPRINKLER SYSTEM
	X		X N			K0062-SPRINKLER SYSTEM MAINTENANCE
	X		X N			K0064-PORTABLE FIRE EXTINGUISHERS
	X		X N			K0104-PENETRATIONS OF SMOKE BARRIERS
	X		X N			K0130-OTHER

EDITION OF LSC APPLIED

85 NEW	85 NEW	2000 EXIS	2000 EXIS	CURRENT SURVEY	PLAN/DATE OF CORRECTION	LSC DEFICIENCIES - BLDG NO. 02
PRIOR 3 SURVEY	PRIOR 2 SURVEY	PRIOR 1 SURVEY	CURRENT SURVEY	PLAN/DATE OF CORRECTION		
12/2001	11/2002	12/2003	10/21/2004			
	X		X C	10/30/2004		K0025-SMOKE PARTITION CONSTRUCTION
	X		X C			K0047-EXIT SIGNS
	X		X C			K0052-TESTING OF FIRE ALARM
	X		X C			K0072-FURNISHING AND DECORATIONS
	X		X C			K0073-FLAMMABLE FURNISHINGS
	X		X C			K0130-OTHER

C=DATE OF CORRECTION N=NO DATE GIVEN P=PLAN OF CORRECTION R=REFUSED TO CORRECT W=WAIVED F=FSSES X=DEFICIENT
COP = CONDITION REQ = REQUIREMENT

TYPE OF DEFICIENCY	CURRENT SURVEY	PRIOR 1 SURVEY	PRIOR 2 SURVEY	PRIOR 3 SURVEY
CONDITION	0	0	0	0
REQUIREMENT	2	4	0	3
HEALTH TOTAL	2	4	0	3
LIFE SAFETY CODE	6	9	4	2
LIFE SAFETY CODE + HEALTH	8	13	4	5

COMPLAINT SURVEY INFORMATION

SURVEY DATE	STATUS
02/12/2003	UNSUBSTANTIATED
11/24/2003	UNSUBSTANTIATED
04/20/2005	SUBSTANTIATED
09/22/2005	UNSUBSTANTIATED

FMS SURVEY INFORMATION

SURVEY DATE	TYPE OF SURVEY
12/15/2004	COMPARATIVE